HOTMARK

CONFIDENCE IN TEXTILES
Tested for harmful substances
according to Oeko-Tex® Standard 100
CQ 909/1 IFTH

CLASS 1

POLYURTHAN	150°- 160°C	PEEL : COLD	Flex Blade 45° Medium Pressure	50 - 60 µm	15 - 20 Sc

SPECIFICATIONS

THICKNESS: Polyurethane 50 - 60 microns

CARRIER: Adhesive & Transparent polyester

CERTIFICATES: Oeko-Tex Label Standard 100 Class I

APPLICATION

1. Cut the material in reverse with a Flex regular blade
2. Weed the excess material
3. Heat press on a SEFA machine on the garment at 150-160° C & Protect the polyester carrier with silicone paper
   15 -20 sec - medium pressure
4. Peel the carrier off when cold

APPLIES ON

Cotton • Polyester • Acrylic & Similar Fibres

CARE & MAINTENANCE

- Always respect the garment's instructions
- Allow 24 hours after application before washing
- Iron the backside only

WASH

- Max 80° C
- Preferably inside out
- Do not bleach
- Tumble-dry approved
- Dry-cleaning approved

STORE

- Up to 1 year
- In a dry room (15-30° C)
- Away from sunlight
- In vertical position